



United States Steel Corporation
Clairton Works
400 State Street
Clairton, PA 15025

March 16, 2010

Mr. Ed Peresie
Department of Air Quality
Bureau of Air Pollution Control
301 Thirty-Ninth Street
Pittsburgh, PA 15201

U.S. Environmental Protection Agency
Region III
Air, Radiation & Toxics Division
1650 Arch Street
Philadelphia, PA 19103-2029
ATTN: James W. Hagedorn (3AT23)

Assistant Council
Department of Environmental Protection
Southwest Region
400 Waterfront Drive
Pittsburgh, PA 15222-4745
ATTN: Steve Hepler

Department of Justice
Environmental and Natural Resource Division
Environmental Enforcement Section
P.O. Box 7611
Ben Franklin Station
Washington, D.C. 20044
ATTN: David Street, Esq.

Subject: USS Reference Number: 10-0137
ACHD Reference Number: 12380
Sulfur Plant
USS Clairton Works

Gentlemen:

The attached form confirms our verbal report of the subject incident. Any questions concerning this matter should be referred to Coleen M. Davis at 412-233-1015.

Sincerely,

Mark G. Tabler
Plant Manager
Clairton Works

RECEIVED

MAR 26 2010

3P

RECEIVED

MAR 26 2010

3AP20

NOTICE OF PLANNED OUTAGE OF EQUIPMENT
ARTICLE XXI - SECTION 2108.1

1. USS Reference Number: 10-0137
ACHD Reference Number: 12380
2. Date & Time of Breakdown: Date: 03/18/10 Time: 1245 hours
3. Company Name: U.S. Steel Corporation - USS Clairton Works
4. Specific Equipment Involved or Affected: Sulfur Plant
5. BAPC Permit Number (if applicable):
6. Location: Clairton, PA
7. Nature and cause of breakdown: Gas flow through the Sulfur Plant was disrupted when the C658 sulfur plant stripper vacuum axi tripped off line. The cause is still under investigation.
8. Identification of Emissions:
 - A. Type(s) (CO, NOX, SO₂, Particulates, Hydrocarbons, etc.)
Hydrogen Sulfide in the down river gas, causing higher SO₂ at the combustion points.
 - B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). SO₂ is an eye, nose, and throat irritant.
 - C. Amount of each type emitted (or likely to be emitted).
Light to Moderate
9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so).
The axi was brought on line and full gas flow restored to the plant.
10. Facility back in operation - Date: 03/18/10 Time: 1247 hours

Signature Coleen M. Davis Date 3-22-10
Coleen M. Davis
Senior Environmental Control Engineer Phone: 412-233-1015